



# IST Operations weekly report

Xiaozhi

- ✓ Just one call from the shifter (MaRongrong)  
Gerrit turn off the the IST cooling pump. But forgot to tell the shift leader
- ✓ IST cooling fluid has been Refilled, the Reservoir Level up to ~80% from ~45% the first fill
- ✓ In principle, the IST performance well, don't have urgent problem.
- ✓ Gerrit always complain the IST slow contral for the IST Readout. Try to separate the alarm from three crate respective ,and more information instead of just turn on/off, (he suggest let me try to fix)



The IST Cooling neck fluid leaking point(left plot), the problem the The O-ring( #18 on the right plot) broken. Gerrit asked the company who send the pump will send us 8 new O-ring for free.

Keep on check the IST on line db\_plots at least two times everyday,( in the morning open eye, and before go to bed),

Check the shift log/summary

Ask Gerrit some thing unclear to me in his documentation, or some thing wrong, he promised he will update it, but it is still looks the same with previous